

Product Discontinuance Notification—PDN# **0000412646**

June 07, 2024

Dear Valued Customer,

We would like to inform you that Moxa is going to discontinue the old CCS model name and its part number of our IPC because of a new CTOS system. This process will begin June 17, 2024.

If you need any of these discontinued products for an existing project, please contact your Moxa sales representative to place orders before June 30, 2024. Also, please note that last-buy orders may be subject to availability.

Please review the details below to determine how these discontinuances will affect your products and/or operations.

Which products will be discontinued?

The following products will be discontinued. Also, see the models recommended to replace the soon to-be-discontinued models, as well as when the replacement models will be available for order.

| Discontinued | Recommended Replacement | Available for Order |
|-----------------------------|------------------------------------|---------------------|
| V3210-TL1-4L-T (CTO) | V3210 (CTO) | Available in July |
| V3210-TL3-4L-CT-T (CTO) | V3210 (CTO) | |
| V3210-TL7-4L-T (CTO) | V3210 (CTO) | |
| V3210-TL1-8L-CT-T (CTO) | V3210 (CTO) | |
| V3210-TL5-8L-CT-T (CTO) | V3210 (CTO) | |
| V3210-TL7-8L-CT-T (CTO) | V3210 (CTO) | |
| V3210-TL7-8L-TSN-CT-T (CTO) | V3210 (CTO) | |
| V3210-TL3-4L-T (CTO) | V3210 (CTO) | |
| V2201-T (CTO) | V2201 (CTO) | Available Now |
| V2403C-T (CTO) | V2403C (CTO) | |
| V2406C-CT-T (CTO) | V2406C-KL (CTO) V2406C-WL (CTO) | |
| V2406C-T (CTO) | V2406C-KL (CTO) V2406C-WL (CTO) | |
| DA-681C-T (CTO) | DA-681C (CTO) | |
| DA-682C-T (CTO) | DA-682C (CTO) | |
| DA-820C-T (CTO) | DA-820C (CTO) | |
| MC-1122-E4-TPM-T-US (CTO) | MC-1122-E4-TPM-T-US (Custom) | |

| | | |
|-------------------------|--------------------------|--|
| MC-1220-T-S (CTO) | MC-1200 (CTO) | |
| MC-3201-TGL7-S-S (CTO) | MC-3201 (CTO) | |
| MPC-2070-E2-T (CTO) | MPC-2070 (CTO) | |
| MPC-2120-E2-T (CTO) | MPC-2120 (CTO) | |
| MPC-2120-E4-T (CTO) | MPC-2120 (CTO) | |
| UC-3111-T-US-LX (CTO) | UC-3111-T-US-LX (Custom) | |
| UC-3111-T-EU-LX (CTO) | UC-3111-T-EU-LX (Custom) | |
| UC-3111-T-AP-LX (CTO) | UC-3111-T-AP-LX (Custom) | |
| UC-8210-T-LX-S (CTO) | UC-8200 (CTO) | |
| UC-8220-T-LX (CTO) | UC-8200 (CTO) | |
| UC-8220-T-LX-US-S (CTO) | UC-8200 (CTO) | |
| UC-8220-T-LX-EU-S (CTO) | UC-8200 (CTO) | |
| UC-8220-T-LX-AP-S (CTO) | UC-8200 (CTO) | |
| UC-8410A (CTO) | UC-8410A (Custom) | |
| UC-8410A-T (CTO) | UC-8410A-T (Custom) | |

Applicable differences in specifications

The difference between the discontinued products and the recommended replacement products is only the model's name and the part number. The orders would be processed via the new CTOS system.

Please note that all service rules (e.g., warranty) still apply to discontinued products.

If you have any questions, please contact:

DA Series: Chengyun Hsi at chengyuncy.hsi@moxa.com,

V Series: Doreen Tsao at doreenfy.tsao@moxa.com

MC 1100/1200 Series: Howard Lu at howardhw.lu@moxa.com

MC-3201 Series: Victor Yu at victorhl.yu@moxa.com

MPC Series: Jamie Chang at jamiETF.chang@moxa.com

UC 8200 Series: Sara Chen at sarach.chen@moxa.com

UC 3100/8400 Series: Amily Wu at amilyyh.wu@moxa.com

or contact your regional sales representative.